ENVIRONMENTAL CHEMISTS

Client:

Analysis For Total Metals By EPA Method 200.8

 Client ID:
 M09350

 Date Received:
 08/09/12

 Date Extracted:
 08/09/12

 Date Analyzed:
 08/10/12

 Matrix:
 Water

 Units:
 ug/L (ppb)

 Project:
 Metro Self Monitor M09350, F&BI 208122

 Lab ID:
 208122-01 10x

 Data File:
 208122-01 10x.038

 Instrument:
 ICPMS1

 Operator:
 btb

Alaskan Copper Works

Lower Upper Internal Standard: % Recovery: Limit: Limit: Germanium 71 60 125

 Concentration

 Analyte:
 ug/L (ppb)

 Chromium
 303

 Nickel
 221

 Copper
 435

 Zinc
 30.3

ENVIRONMENTAL CHEMISTS

Analysis For Total Metals By EPA Method 200.8

Client ID: Method Blank Date Received: Not Applicable Date Extracted: 08/09/12 08/10/12 Date Analyzed:

Matrix: Water Units: ug/L (ppb)

Internal Standard:

Germanium

Client: Project: Lab ID:

Alaskan Copper Works Metro Self Monitor M09350, F&BI 208122

I2-526 mb

Data File: Instrument:

I2-525 mb.041 ICPMS1

Operator: btb

Lower

% Recovery:

Limit: 60

 ${\bf Upper}$ Limit:

125

Concentration

87

Analyte: ug/L (ppb)

Chromium <1 Nickel <1 Copper <1 Zinc <1

ENVIRONMENTAL CHEMISTS

Date of Report: 08/14/12 Date Received: 08/09/12

Project: Metro Self Monitor M09350, F&BI 208122

QUALITY ASSURANCE RESULTS FOR THE ANALYSIS OF WATER SAMPLES FOR TOTAL METALS USING EPA METHOD 200.8

Laboratory Code: 208006-01 (Matrix Spike)

Analyte	Reporting Units	Spike Level	Sample Result	Percent Recovery MS	Percent Recovery MSD	Acceptance Criteria	RPD (Limit 20)
Chromium	ug/L (ppb)	20	<1	76	75	71-130	1
Nickel	ug/L (ppb)	20	2.24	71	66 vo	71-120	7
Copper	ug/L (ppb)	20	<1	74	69	52-134	7
Zinc	ug/L (ppb)	50	26.2	67 b	122 b	51-142	58 b

Laboratory Code: Laboratory Control Sample

	Percent											
	Reporting	Spike	Recovery	Acceptance								
Analyte	Units	Level	LCS	Criteria								
Chromium	ug/L (ppb)	20	101	80-119								
Nickel	ug/L (ppb)	20	100	83-119								
Copper	ug/L (ppb)	20	98	81-120								
Zinc	ug/L (ppb)	50	100	82-120								

ENVIRONMENTAL CHEMISTS

Data Qualifiers & Definitions

- a The analyte was detected at a level less than five times the reporting limit. The RPD results may not provide reliable information on the variability of the analysis.
- A1 More than one compound of similar molecule structure was identified with equal probability.
- b The analyte was spiked at a level that was less than five times that present in the sample. Matrix spike recoveries may not be meaningful.
- ca The calibration results for this range fell outside of acceptance criteria. The value reported is an estimate.
- c The presence of the analyte indicated may be due to carryover from previous sample injections.
- d The sample was diluted. Detection limits may be raised due to dilution.
- ds The sample was diluted. Detection limits are raised due to dilution and surrogate recoveries may not be meaningful.
- dv Insufficient sample was available to achieve normal reporting limits and limits are raised accordingly.
- fb Analyte present in the blank and the sample.
- fc The compound is a common laboratory and field contaminant.
- hr The sample and duplicate were reextracted and reanalyzed. RPD results were still outside of control limits. The variability is attributed to sample inhomogeneity.
- ht Analysis performed outside the method or client-specified holding time requirement.
- ip Recovery fell outside of normal control limits. Compounds in the sample matrix interfered with the quantitation of the analyte.
- j The result is below normal reporting limits. The value reported is an estimate.
- J The internal standard associated with the analyte is out of control limits. The reported concentration is an estimate.
- jl The analyte result in the laboratory control sample is out of control limits. The reported concentration should be considered an estimate.
- jr The rpd result in laboratory control sample associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- js . The surrogate associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- lc The presence of the compound indicated is likely due to laboratory contamination.
- L The reported concentration was generated from a library search.
- nm The analyte was not detected in one or more of the duplicate analyses. Therefore, calculation of the RPD is not applicable.
- pc The sample was received in a container not approved by the method. The value reported should be considered an estimate.
- pr-The sample was received with incorrect preservation. The value reported should be considered an estimate.
- ve Estimated concentration calculated for an analyte response above the valid instrument calibration range. A dilution is required to obtain an accurate quantification of the analyte.
- vo The value reported fell outside the control limits established for this analyte.
- x The sample chromatographic pattern does not resemble the fuel standard used for quantitation.

.bc.*				(100	1.0	* *,											•	e e				
										•				M05380					City, 11 SEATTLE WA 98/34 206-57-6033, 206-382-8309	628 S.	DARRED TO THE STATE OF THE STAT	208122
										شار شاران الماران			, '	10		<u> </u>			77.e WA	1	a JADAPSOC	
				, Y. Y.		Pentachicasi Talian (S. 1975)				e e				8//h		Ĩ			285-90 1-385	25	CHOMES	
		5.		1	1. 11		,							12:30		7			58134 58134	8		Æ
	1			H										tho		Ţ			C account	metro	PROJECT NAMEANO.	SAMPLE CHAIN OF CUSTORY
		2 2)	Genera			_	-	-			_	_	_			<u>1</u>		H	6	Self	T NAME	EAN
		- 1		THE STATE OF			_	_	_	_		_		1		Ŀ		Ц		2 Mis	8	9
		4	Thopso						L						10	<u> </u>				Morital.		3
. 			_					上							AOX						V	
							L	L	L											05250W	*	ME
		十八	8	8	<u></u>	_	-	-	-	-	-	-	_	X	Occ	u M	CZ~			320	5	20-80
	•	8.2	C .	18				T						1+					000	1 =	w	702
22							L		L	L		L	L	L				6	1		Fla	7 6
3		"	8/1/28	DATE		H	+	+	+	2	+	+	+		_	F1 - 222			4		P. 67	
		1/			***								2.5			Ŧ			i		18	*
		4.80	22:1			- 10			- 2							•			E		-	1

ENVIRONMENTAL CHEMISTS

James E. Bruya, Ph.D. Yelena Aravkina, M.S. Bradley T. Benson, B.S. Kurt Johnson, B.S. 3012 16th Avenue West Seattle, WA 98119-2029 TEL: (206) 285-8282 e-mail: fbi@isomedia.com

August 14, 2012

Gerald Thompson, Project Manager Alaskan Copper Works 628 South Hanford Seattle, WA 98134

Dear Mr. Thompson:

Included are the results from the testing of material submitted on August 9, 2012 from the Metro Self Monitor M09350, F&BI 208122 project. There are 4 pages included in this report. Any samples that may remain are currently scheduled for disposal in 30 days. If you would like us to return your samples or arrange for long term storage at our offices, please contact us as soon as possible.

We appreciate this opportunity to be of service to you and hope you will call if you have any questions.

Sincerely,

FRIEDMAN & BRUYA, INC.

Michael Erdahl Project Manager

Enclosures ACU0814R.DOC